

Work Order ID 112079

112079

Page 1

Monday, February 03, 2014 1:58:50 PM

Item ID: D2168 Accept *N900040100* Setup Start *NS1*

Revision ID: Stop *NS2*

Item Name: Step End Caps

Start Date: 1/29/2014 Start Qty: 2.00 *2*

Required Date: 1/30/2014 Req'd Qty: 2.00 *2*

Reference: RMA RA111644

Cust Item ID:

Customer: CHINT01

Approvals: Process Plan: MF Date: 14-2-3 Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start *NR1*

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

100		0.00	DAS	27					
100		0.00		9-89					
QC	Memo								
Quality Control	INSPECT RA 111644 D2168 X 2 B2243								
	PART IS GOOD								
	ID AND STOCK UNDER NEW BATCH NUMBER								

110	Identify as per dwg & Stock Location: <u>Merr</u>	0.00							
110		0.00							
Packaging	Memo								
Packaging									

120	QC21- Final Inspection - Work Order Release	0.00							
120		0.00							
QC	Memo								
Quality Control									

14-02-05

14-02-04

DAS
28
9-89

Picklist Print

Monday, February 03, 2014 1:58:44 PM

Page 1

Work Order ID: 112079

Parent Item: D2168

Parent Item Name: Step End Caps

Start Date: 1/29/2014

Required Date: 1/30/2014

Start Qty: 2.00

Required Qty: 2.00

Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2168 Step End Caps		Manufactured	No				Each	16.0000		2			

Location

Loc Qty

Loc Code

Mezz

2243

16

16

CMF 14-2-3

RA 111644 D2168 B2243

Received @ Dart November 4th, 2013
Inspected @ Dart January 21st, 2014

CUSTOMER: HELI INTER INC
CUSTOMER CONTACT: PASCAL DEMERS
SHIPPED FROM: ST HUBERT QC, CANADA

Instructions for RA 111644 D2168 B2243

- Correct part to drawing
- Return to stock under new Batch #

Time Estimate = 1 HOURS

Departments Required: Stores

Pictures Attached = NO

QTY INSPECTED = x2 D2243 B2243

D2168

7-A 10-14

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**

